

## OVER AND ABOVE FUNDING

**Region:** 5

**Location:** MD066

**CSS #** 31907

**Maximo Work Order No.:** 14685

**Asset #:** NA

**Date Issued:** 08/23/2021

**Original Description:** Bearings are going bad on cooling tower drive line up top

**Repairs Needed:**

S&S proposes to remove and replace QTY 2 gearducers and belts on the cooling tower. S&S will then complete a system check to ensure the system is running properly.

### RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	Parts ( See detail in attached Quote)	--	--	\$7,684.01	--	\$7,684.01
--	NA	SS Labor	24	\$100.00	--	--	\$2,400.00
--	NA	Diagnosis	1	\$200.00	--	--	\$200.00

### Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
25	\$2,600.00	\$7,684.01		\$10,284.01	106%	\$10,901.05

