

Additional Funding Request

Submitted: 09/28/2021

MD066- CAC Lock	CSS # 32584 WO# 15109								
Description of Repairs	S&S proposes to replace the lock set on the OMG building.								
Original SC Investigative Diagnosis	\$320.00								
Diagnosis: Initial Work Order	There is a non-functioning CAC lock in the OMS building. It is an exterior lock that is not securing. The unit has positioned in front of the door so that I cannot be opened.								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$518.00</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Lock/Shipping</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;">\$518.00</td> <td style="text-align: left; padding: 2px;">\$518.00</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Lock/Shipping	1	\$518.00	\$518.00
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Lock/Shipping	1	\$518.00	\$518.00						
Additional Labor Cost to Perform Repairs	<p>Labor: \$400.00 5 hours each/General Maint. Rate \$80.00 per hour = \$400.00</p>								
Total Cost of Repair	\$1,238.00								