

## **Additional Funding Request**

Submitted: 10/12/21

<b>MD066-Condesation Drain Pan lines</b>	<b>CSS #30243 WO#14148</b>										
Description of Repairs	Repair condensations drain lines of Heat Pumps 1 thru 12										
Original SC Investigative Diagnosis	\$NA										
Diagnosis: Initial Work Order	Repair condensations drain lines of Heat Pumps 1 thru 12										
Explanation of Additional Costs for Repairs	N/A										
Additional Material Cost to Perform Repairs	<b>Materials: \$ 61.78</b> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts (See Attached)</td> <td style="text-align: left; padding: 2px;">1</td> <td style="text-align: left; padding: 2px;"></td> <td style="text-align: left; padding: 2px;"><b>61.78</b></td> </tr> </tbody> </table>			ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts (See Attached)	1		<b>61.78</b>
ITEM	QUANTITY	UNIT PRICE	TOTAL								
Parts (See Attached)	1		<b>61.78</b>								
Additional Labor Cost to Perform Repairs	<b>Labor: \$</b> 12 Hours Rate \$80.00 per hour = \$960.00										
<b>Total Cost of Repair</b>	<b>\$1,021.78</b>										