

Region: 5

Location: MD066

CSS # 35101

Maximo Work Order No.: 16886

Asset #: NA

Date Issued: 05/23/22

Original Description: CAC System not working properly, Intermittent deficiencies. Some cards work fine then the next time will not work at all.

Repairs Needed:

See attached document for work to be performed

RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	See detail in attached QUOTE	--	--	\$3,235.00	--	\$3,075.00
--	NA	Labor			--	--	\$3,485.00

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment	Total Cost	CE Factor	Total Estimate
	\$3,485.00	\$3,075.00		\$6,560.00	106%	\$6,953.60