



Moore's Electrical & Mechanical Construction, Inc.

SERVICE INVOICE: 447141

BILL TO:
INTER002
INTERNATIONAL SUPPORT GROUP
9000 SHERIDAN ST SUITE 172
PEMBROKE PINES, FL 33024

SHIP TO:
8233114
ISG USARC VA099 BEDFORD
1117 HARMONY LANE
BEDFORD, VA 24523

<u>INVOICE DATE</u>	<u>CUSTOMER PO</u>	<u>PAYMENT TERMS</u>	<u>REFERENCE #</u>	<u>WORKORDER #</u>	<u>CONTRACT ID</u>
08/29/2019	19444	Due in 30 Days		COM0113778	
Pages 1 of 1					
<u>ITEM ID</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>SERV DATE</u>	<u>UNIT PRICE</u>	<u>EXT PRICE</u>
CLABOR-PLMB-REG	REGULAR PLUMBING LABOR	3.00	8/12/2019	120.00	360.00
CMISCX-NON-STOCK ITEM	3/4X10 BLK IRON	1.00		25.06	25.06
					0.00

CSS 19444 EXTEND BOILER BLOW DOWNS

8/12/19 - Went to site. Picked up screw pipe from vendor. Cut to length, and screwed to relief valve assembly. Complete

For questions regarding commercial invoices please contact our Accounts Receivables Department at 434-309-2581. Past 30 Days invoices are subject to 1.5% monthly interest charge. Additional charges for payments made by credit card may apply. We accept VISA, Master Card, Discover and American Express. Late payments sent to collections or legal process will also result in additional charges.

Sales Total	385.06
Disc.	0.00
Tax Total	0.00
Net Amount Due	\$385.06



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Christiansburg, VA

Falmouth, VA • Lynchburg, VA • Richmond, VA • Greensboro, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
Customer: INTERNATIONAL SUPPORT GROUP Address: 9000 SHERIDAN ST Phone: PEMBROKE PINES FL 33024 954-900-1095	Customer: ISG USARC VA099 BEDFORD Address: 1117 HARMONY LANE Phone: BEDFORD VA 24523 8045855211
Service Call #: COM0113778	Call Type: COM-PLMB

Service Requested
CSS 19444 EXTEND BOILER BLOW DOWNS
WO#: 5-9575, Location: VA099-01 Bedford USARC - Bldg 01 - Reg 5 - Z3, Description: Safety relief valve must be piped so that there is no danger of scalding attendants.
WO#: 5-9578, Location: VA099-01 Bedford USARC - Bldg 01 - Reg 5 - Z3, Description: Safety relief valve must be piped so that there is no danger of scalding attendants (discharge pipe within 4" of the floor).

Problems
Description Tech Equip. Desc and Model Manufacturer Equip. Serial Asset ID PIPING MARKYOUNGE

Tech Notes
8/12/19 - Went to site. Picked up screw pipe from vendor. Cut to length, and screwed to relief valve assembly. Complete

Labor
Date Technician Description Hours 8/12/2019 Mark Younger COMMERCIAL TRAVEL TIME 0.50
8/12/2019 Mark Younger REGULAR PLUMBING LABOR 2.50

Materials
Date Part Number Description Quantity 8/12/2019 CMISCX-NON-STOCK ITEM Items for PO 202419 1.000

Signed By	Don	Signature		Date	8/12/2019
-----------	-----	-----------	--	------	-----------

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: B01|R5|23 Date of Visit: 08/12/19

Contractor Personnel on Site:

1. MARK YOUNGER 2. _____

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. wo# 5-9575 j 5-9578

Service Calls – Service Call Number and Description

1. CSS# 19444 - blow down repairs
2. CSS# _____
3. CSS# _____

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: MARK YOUNGER Date: 8/12/19

Signed: _____

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Donald L. Wilson Date: 12 Aug 19, completed

Signed: Donald L. Wilson 28 Aug 19

E-Mail: _____