



Moore's Electrical & Mechanical Construction, Inc.

SERVICE INVOICE: 447708

**BILL TO:**  
INTER002  
INTERNATIONAL SUPPORT GROUP  
9000 SHERIDAN ST SUITE 172  
PEMBROKE PINES, FL 33024

**SHIP TO:**  
82333367  
ISG USARC VA048 RICHMOND  
1741 EAST BELT BOULEVARD  
BUILDINGS 1 & 2  
RICHMOND, VA 23224

<u>INVOICE DATE</u>	<u>CUSTOMER PO</u>	<u>PAYMENT TERMS</u>	<u>REFERENCE #</u>	<u>WORKORDER #</u>	<u>CONTRACT ID</u>
09/05/2019	20303	Due in 30 Days		COM0115634	
Pages 1 of 1					
<u>ITEM ID</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>SERV DATE</u>	<u>UNIT PRICE</u>	<u>EXT PRICE</u>
CLABOR-HVAC-REG	REGULAR HVACR LABOR	3.00	8/28/2019	120.00	360.00
TAX 0.00					

PO 20303

8/28/2019 MOD pointed out A/C not working in RM#206. Found mini-split missing voltage. After lots of searching, finally was able to find tripped breaker. Unit supplied with two single pole breakers. Reset breaker and checked mini-split operation. This work order is complete.

For questions regarding commercial invoices please contact our Accounts Receivables Department at 434-309-2581. Past 30 Days invoices are subject to 1.5% monthly interest charge. Additional charges for payments made by credit card may apply. We accept VISA, Master Card, Discover and American Express. Late payments sent to collections or legal process will also result in additional charges.

Sales Total	360.00
Disc.	0.00
Tax Total	0.00
<b>Net Amount Due</b>	<b>\$360.00</b>



Proudly serving the entire states of Virginia & North Carolina.

Altavista, VA • Charlottesville, VA • Chesapeake, VA • Christiansburg, VA

Falmouth, VA • Lynchburg, VA • Richmond, VA • Greensboro, NC

P.O. Box 119 • Altavista, VA • 800.789.7199 • service@mooreselectric.com

Billing Address	Site Address
<b>Customer:</b> INTERNATIONAL SUPPORT GROUP <b>Address:</b> 9000 SHERIDAN ST <b>Phone:</b> PEMBROKE PINES FL 33024 954-900-1095	<b>Customer:</b> ISG USARC VA048 RICHMOND <b>Address:</b> 1741 EAST BELT BOULEVARD <b>Phone:</b> RICHMOND VA 23224
<b>Service Call #:</b> COM0115634	<b>Call Type:</b> COM-HVAC

#### Service Requested

THERE IS A CONDENSING UNIT THAT HAS POWER BUT IS NOT CUTTING ON.

#### Problems

Description	Tech	Equip. Desc and Model	Manufacturer	Equip. Serial	Asset ID
TROUBLE SHOOT UNIT	MIKE CIMINO	Room 207 Mini-split(outdoor) M#AOU18RLX	Fujitsu	CQN005388	

#### Tech Notes

8/28/2019 MOD pointed out A/C not working in RM#206. Found mini-split missing voltage. After lots of searching, finally was able to find tripped breaker. Unit supplied with two single pole breakers. Reset breaker and checked mini-split operation. This work order is complete.

#### Labor

Date	Technician	Description	Hours
8/28/2019	Michael Cimino	REGULAR HVACR LABOR	3.00

#### Materials

Date	Part Number	Description	Quantity
No records found			

Signed By	Andrew Campbell	Signature		Date	8/28/2019
-----------	-----------------	-----------	--	------	-----------

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: 1 Date of Visit: 8/28/19  
Contractor Personnel on Site:

1. Michael Cimino 2. Chase Davis

### Work Performed:

**Preventive Maintenance** - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# \_\_\_\_\_

### Service Calls – Service Call Number and Description

1. CSS# 20303 There is a condensing unit that has power but is not cutting on \_\_\_\_\_
2. CSS# \_\_\_\_\_
3. CSS# \_\_\_\_\_

---

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Michael Cimino Date: 8/28/19

Signed: Michael Cimino

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Scott Grenier /RFOS Date: 30 Aug 2019

Signed: Scott Grenier

E-Mail: \_\_\_\_\_