

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY023-118

LOCATION/RM #: BLDG -118

**MECHANIC  
SIGNATURE:** *Deen Rowe*

**DATE:** 9/1/22

**START TIME:** 1pm

**FINISH TIME:** 2pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-118	18937	IL-14			Interior Light in Building NY023-118	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

*All lights work, two out of three hallway motion sensors don't work.*

