

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building:

Date of Visit: 7/3/23

Contractor Personnel on Site:

1. Deen Rowe 2. \_\_\_\_\_

### Work Performed:

**Preventive Maintenance** - (Annual, Quarterly, Monthly, equipment identification, etc.)  
**Service Orders** -

PM/SO	WO #	Asset #	PM #	Asset Description
	22927	9312	PM-AN-9312	J-25 1-pc Overhead Crane
	22928	9313	PM-AN-9313	J-26 2-pc Lavatory, Wall Mounted Rm 102
	22929	9314	PM-AN-9314	J-26 1-pc Urinal, Wet, Flush Valve Rm 102
	22930	9315	PM-AN-9315	J-26 1-pc Toilet, Flush Valve, Wall Mounted Rm 102
	22931	9316	PM-AN-9316	J-26 1-pc Lavatory, Wall Mounted Rm 103
	22932	9317	PM-AN-9317	J-26 1-pc Toilet, Flush Valve, Wall Mounted Rm 103
	22933	9318	PM-AN-9318	J-26 1-pc Janitor Sink, Wall Mounted Rm 1013
	23128	IL-15	PM-MO-IL-15	Interior Light in Building NY023-121
	23232	9328	PM-SA-9328	J-52 5-pc Overhead Door, Steel, Roll Up, 16Wx14H
	23233	9329	PM-SA-9329	J-52 1-pc Overhead Door, Steel, Roll Up, 12Wx12H
	23234	9330	PM-SA-9330	J-52 6-pc Overhead Door, Steel, Roll Up, 16Wx16H

---

### CERTIFICATION OF WORK

To be signed by the Contractor:


Print Name: Deen Rowe \_\_\_\_\_ Date: 7/11/23

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline.

Signed: 

To be signed by Facility Manager:

Print Name/Rank: SEAN MC BAIN Date: 7/11/23

Signed: 

E-Mail: Sean.M.Bain.cfr@army.mil