

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
Interior LIGHTING

SITE AND BLDG #: NY023-121

**MECHANIC
SIGNATURE:**

Deen Rowe

DATE: 9/2/22

LOCATION/RM #: Bldg - 121

START TIME: 1:30 pm

FINISH TIME: 2 p

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-121	18938	IL-15				Interior Light in Building NY023-121
			2	T8- 4ft	Vehicle Bay	Lift Needed
			6	T4 - 4ft	Small vehicle Bay	Ballast Issues
			8	T4- 4ft	Open Area	Ballast Issues

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

