

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-121

LOCATION/RM #: Building 121

MECHANIC

SIGNATURE: DeGrawgham Rose

DATE: 11/8/22

START TIME: 8 Am

FINISH TIME: 9 Am

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-121	19470	IL-15			Interior Light in Building NY023-121	
			11	T-5	Room 1011 (gym)	Maybe Ballast Issues
			6	T-5	Vehicle Bay	Maybe Ballast Issues
			2	T-5	Main Vehicle Bay	Maybe Ballast Issue

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Will get Lift and Complete by Nov 31, 2022.

