

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-121

MECHANIC
SIGNATURE: *Dean Rone*

DATE: 2/2/23

LOCATION/RM #: Building 121

START TIME: 8Am

FINISH TIME: 10Am

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-121	20726	IL-15			Interior Light in Building NY023-121	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- 3 ballast out in gym area.
- 2 ballast out in Vehicle Bay

