

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY0023-121

MECHANIC  
SIGNATURE: *Deen Row*

DATE: 3/2/23

LOCATION/RM #: *Building 121*

START TIME: 8AM

FINISH TIME: 9AM

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-121	21199	IL-15			Interior Light in Building NY023-121	
			4	T5, 4ft		Lift Needed
			10	T5, 4ft		Lift Needed
			2		Ballast issue	Electrician

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- Next lift after Lighting will be  
complete.

