

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY023-123

LOCATION/RM #: Building 123

MECHANIC  
SIGNATURE: Dean Rose

DATE: 8/23/22

START TIME: 1pm

FINISH TIME: 3pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-123	18631	IL-16			Interior Light in Building NY023-123	
			2	T-5 4ft	Room 1013 CAGE	
			2	T-5 4ft	Room 1017 Work bays	
			6	T-5 4ft	Room 1022 Veh. Bay	
			4	T-5 4ft	Room 1019 Ins. Bay	
			1	2 ft LED	HALLWAY	
			1	4ft LED	HALLWAY	
			2	2 ft LED	Room 1010 Common Office	
			1	2 ft LED	ARMS ROOM	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Lift Needed

Vehicle Bay - 40 - T5 4ft lights, May need ballast because both lights are out.

