

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

To be signed by the Contractor:

Print Name: DEEN ROWE Date: 9-14-2020

Signed: Deen Rowe

To be signed by Facility Manager:

Print Name/Rank: _____ Date: _____

Signed: LINN.RYAN.G.1037390832 Digitally signed by LINN.RYAN.G.1037390832
Date: 2020.09.29 17:27:00 -04'00'

E-Mail: _____

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023-200 Date of Visit: 09/14/2020

Contractor Personnel on Site:

1. DEEN ROWE 2. _____

Work Performed:

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)
Service Orders -

PM/SO	WO #	Asset #	PM #	Asset Description
	9768	190917-179	PFQ190917179	6-pc ptac 2nd floor INDOOR
	9768	190917-180	PFQ190917179	7-pc ptac 1st floor
X	9952	9425	PM-FQT-9425	J-04 1-pc Air Handler
	9953	9433	PM-FQT-9433	J-09 8-pc PTAC INDOOR
X	10155	9425	PM-SA-9425	J-04 1-pc Air Handler
	10156	9433	PM-SA-9433	J-09 8-pc PTAC INDOOR
	10157	9436	PM-SA-9436	J-15 1-pc Mini Split INDOOR
X	10215	190917-174	PMS190917174	1-pc Condensation Unit
X	10215	190917-175	PMS190917174	1-pc Condensation Unit
X	10215	190917-176	PMS190917174	1-pc Condensation Unit
X	10215	190917-177	PMS190917174	1-pc Condensation Unit
X	10215	190917-178	PMS190917174	1-pc Condensation Unit
	10215	190917-179	PMS190917174	6-pc ptac 2nd floor INDOOR
	10215	190917-180	PMS190917174	7-pc ptac 1st floor INDOOR

CERTIFICATION OF WORK