

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-200

LOCATION/RM #: Fort Totten

MECHANIC
SIGNATURE: *Deen Lowe*

DATE: 10/1/20

START TIME: 8Am

FINISH TIME:

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-200	10267	190917-182			230-pc 4 foot lights out Not Working	
NY023-200	10267	190917-183			4-pc U shape Not Working	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

4 ft lights out 2nd floor

|||| - Hallway

|| - RPAC

All lights - 2019C

4 - Infant of Bulletin Board

|||| - 2006±

|||

3rd floor

||

U-Shape lights

|||| - Women's Bathroom 2nd floor

||| - Men's Bathroom 2nd floor

||| - Lou's office

* Other offices could not get access to because of Covid-19.