

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
Interior LIGHTING

SITE AND BLDG #: NY023-200

MECHANIC
SIGNATURE:

DEEN Rowe

DATE: 7/13/21

LOCATION/RM #:

Building 200

START TIME: 8am

FINISH TIME: 12pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-200	13950	190917-182			230-pc 4 foot lights out Not Working	
NY023-200	13950	190917-183			4-pc U shape Not Working	
<i>NY023-200</i>	<i>13950</i>	<i>190917-182</i>	<i>82</i>		<i>4-foot</i>	
<i>NY023-200</i>	<i>13950</i>	<i>190917-183</i>	<i>33</i>		<i>U-shaped</i>	
<i>NY023-200</i>			<i>10</i>		<i>2 ft lights</i>	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

4ft lights out

- 1 in front of Room 1032
- 10 in 1st floor hallway
- 6 KANE HALL
- 32 KANE HALL
- 4 in room 1037
- Ballast out in room 101E (retention center)
- Room 2001 4 lights out
- 2005/2006 common space 10 lights out.
- Room 3013C 2 lights out
- Room 3014F 2 lights out.
- Room 3014 2 lights out.
- 24 lights out in 3rd floor Hallway.
- 4 lights out room 3008J

2ft lights out

- 10 in the Gym

U-shape lights

- 6 lights out Men's B. 3rd
- 3 lights out DPW.
- 6 lights out 2nd floor Women's
- 12 lights out on 2nd floor Men's
- 6 lights out Men's Bathroom

- 1 3rd floor women's locker room