

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-200

LOCATION/RM #: Building 200

MECHANIC
SIGNATURE: Deen Rowe

DATE: 9/7/22

START TIME: 8AM

FINISH TIME: 8AM

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-200	18942	IL-19			Interior Light in Building NY023-200	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- Building 200 is under Construction

