

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-206

LOCATION/RM #: Building 206

MECHANIC

SIGNATURE:

Deen Rowe

DATE: 8/25/22

START TIME: 8 AM

FINISH TIME: 9 AM

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-206	18635	IL-20			Interior Light in Building NY023-206	
			1	LED Strip 4ft	1st Floor Hallway	
			2	LED Strip 4ft	Room B05	no power
			1	LED Strip 4ft	Above Water Heater	
			1	LED Strip 4ft	Room B101A	
			4	LED Strip 4ft	Room 307	no power
			2	LED Strip 4ft	Room 305	
			2	LED Strip 4ft	Room 302	
			1	LED Strip 4ft	Room 301	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

