

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-206

LOCATION/RM #: Building 206

MECHANIC
SIGNATURE: Deen Rowe

DATE: 10/3/22 - 10/4/22

START TIME: 3pm

FINISH TIME: 4pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-206	19276	IL-20			Interior Light in Building NY023-206	
			1	LED Strip	1 st floor Hallway	Electrician Needed
			1	LED Strip	3 rd floor Office (Corner)	Electrician Needed

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

