

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-206

LOCATION/RM #: Building 206

MECHANIC
SIGNATURE: Deen Rose

DATE: 3/28/23

START TIME: 8 am

FINISH TIME: 9 am

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-206	21204	IL-20			Interior Light in Building NY023-206	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- 2 LED lights out in hallway.
- 3rd floor office lights are out.

