

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-319

LOCATION/RM #: Building 319 interior

MECHANIC
SIGNATURE: Deen Rowe

DATE: 8/26/22

START TIME: 9AM

FINISH TIME: 1030AM

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-319	18636	IL-21			Interior Light in Building NY023-319	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

- Basement hallway has no light/ power

Electrician Needs

