

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-319

MECHANIC
SIGNATURE: Deen Rose

DATE: 7/7/22

LOCATION/RM #: Building 319

START TIME: 3:15 pm

FINISH TIME: 4pm

| Site Location | WO# | Asset # | Number of lights out | Size, Wattage, and Type | Description | Comments |
|---------------|-------|---------|----------------------|-------------------------|--------------------------------------|----------|
| NY023-319 | 18944 | IL-21 | | | Interior Light in Building NY023-319 | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

N, lighting in basement + hallway, light switch
 (LED strip) don't work

