

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

Interior LIGHTING

SITE AND BLDG #: NY023-319

LOCATION/RM #: Building 319

MECHANIC
SIGNATURE: *Deen Rose*

DATE: *11/10/22*

START TIME: *10am*

FINISH TIME: *11am*

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-319	19476	IL-21			Interior Light in Building NY023-319	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Basement hallway light sensor is out.

