

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY023-329

LOCATION/RM #: Building 329

MECHANIC  
SIGNATURE: *Deen Rose*

DATE: 8/25/22

START TIME: 1:30pm

FINISH TIME: 2pm

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-329	18637	IL-22			Interior Light in Building NY023-329	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

FDNY has keys No longer have  
Access to Building 329

\* Asset # 1C-22 needs to be removed.