

PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST
Interior LIGHTING

SITE AND BLDG #: NY023-330

MECHANIC SIGNATURE: *Deen Rose*

DATE: 11/16/22

LOCATION/RM #: *Building 330*

START TIME: *10Am*

FINISH TIME: *12pm*

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-330	19478	IL-23			Interior Light in Building NY023-330	
			1	LED Strip	Room 208	Electrician Needed
			1	LED Strip	Attic (Army)	Electrician Needed
			2	LED Strip	Attic (BMS)	Electrician Needed
			1	LED Strip	2nd Floor Hallway	Electrician Needed
			1	LED Strip	Room 123	Electrician Needed

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

