

## PREVENTATIVE MAINTENANCE PROGRAM CHECKLIST

### Interior LIGHTING

SITE AND BLDG #: NY023-330

MECHANIC  
SIGNATURE: *Deew Rose*

DATE: 2/14/23

LOCATION/RM #: B. 330

START TIME: 10Am

FINISH TIME: 11Am

Site Location	WO#	Asset #	Number of lights out	Size, Wattage, and Type	Description	Comments
NY023-330	20734	IL-23			Interior Light in Building NY023-330	

Note: The technician shall perform any repairs identified during PM up to \$250 (direct labor and direct material cost) per PM occurrence. For any deficiencies found exceeding \$250 open a corrective maintenance (CM) ticket and include the Asset #, WO #, photos, and a detailed description of the deficiency. To be performed by: General Maintenance Worker **Additional Notes:**

Army Attic has one light out above Air Handlers  
Electrician Needed.