

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: M023 - Building 206

Date of Visit: 7/1/22

Location Address: 206 Duran Rd, Fort Totten, NY

Contractor Personnel on Site:

Deen Rowe

Work Performed: Replace. Fan motor and 1 fan wheel on PTAC unit on 3rd floor.

Service Calls – PO/CSS# 1267


**Please take pictures and send with quote**

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Deen Vaughn Rowe Jr.

Date: 7/1/22


Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Louis Corbo RFOS

Date: 7/6/22

Signed: 

Email: Louis.A.CORBO.CIV@ARMY.MIL

