

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 15794

Maximo Work Order No.: 3408

Asset#: NA

Date Issued: 4/12/19

Original Description: Remove and install new 4 8" fluorescent fixture in back cage area of building 121

Diagnosis:

- 1 foot wide by 4 feet long Light Fixture - LED
- 7 Hours disassemble/reassemble cage – remove top for access to light fixture for replacement.
- 2 men on site.
- All Labor included

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials				\$172.50		\$172.50

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
14 x \$174.26= \$2,440	\$2,440.00	\$172.50		\$2,612.50	.9	\$2,351.25

Please see attached estimate

Note:

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023 Date of Visit: 5/16/19

Contractor Personnel on Site: Elite Comfort Group

1. Travis / CJ 2. Bob Weller

Work Performed:

Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)

1. WO# Survey

Service Calls – Service Call Number and Description

1. CSS# 16945

2. CSS# 18394

3. CSS# 17295

4. CSS 18510 , 17296 Boiler 906 same unit, down with melted cap

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Richard Dumaresq Date: 5/16/19

Signed: Richard Dumaresq

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Louis. A. Corbo AFOS Date: 5/16/19

Signed: Louis A. Corbo

E-Mail: Louis.A.corbo.ctr@mail.mil

Elite Comfort Group

High Performance HVAC

600 Johnson Ave Suite B1
Bohemia, NY 11716
631-319-8311

Date – May 23, 2019

International Support Group
9000 Sheridan St, Suite 172
Pembroke Pines, FL 33024

WO#: 3408
CSS#:15794
FACID: NY023

Subject: Replacement of Light over Cage – Building 121

We offer the following proposal for your consideration

- 1 foot wide by 4 feet long Light Fixture - LED
- 7 Hours disassemble/reassemble cage – remove top for access to light fixture for replacement.
- 2 men on site.
- All Labor included

Totals...Materials - \$172.50; Labor - \$2,440.00 - **Total Repair - \$2,612.50**

Prices are valid for 30 days.

Job related debris will be removed from job site and disposed of properly.

If this proposal is acceptable, please sign and return to us

Sincerely,

Elite Comfort Group

THE ABOVE PROPOSAL IS ACCEPTED AND AGREED TO, INCLUDING ALL PAYMENT TERMS

Signature

Date

Print Name

TERMS: NET 30 DAYS. 1 ½% per month interest charged on all past due balances.

Exclusions: *Controls, failed sensors, if no longer supported, wiring in panels and devices done by others, controllers, computer software, supervisory controllers, devices, starters, VFD's, wire pulls, electrical pathways, IT infrastructure issues, any unforeseen circumstances that cause the system to become non operational or failed parts and time associated to replace.*

For more details about this offer please contact

T. 631-750-9305 or email us Estimating@EliteComfortGroup.com

THANK YOU FOR YOUR BUSINESS.