

Additional Funding Request

Site: NY023	WO# 3172	CSS # 17828	Asset# NA
Description of Repairs	Replacement of damaged office door		
Diagnosis: Initial Work Order CSS# 17828	Repair/Replace damaged office door		
Explanation of Additional Costs for Repairs	Investment is labor and materials to replace damaged office door		
Additional Labor Cost to Perform Repairs	$6 \times \$150.00 = \900.00		
Additional Material Cost to Perform Repairs	\$765.00		
Total Cost of Repair	\$1,665.00		



Quotation for Fort Totten Door Replacement

April 10, 2019

To: International Support Group
Attn: Mr. Mike Wolfe
Email: mwolfe@internationalsupportgroup.com

Location of Work: Fort Totten, NY Building 200, Second Floor, Room # 2025E

Scope of Work

Replace Door Hinges and lock.

Material:

- Door
- Lock
- Hinges
- Paint

Total Cost including labor and materials: \$1,665.00

QUOTATION VALID FOR: 45 Days from Quotation Date

ACCEPTANCE OF QUOTATION:

The above prices, conditions and specification are hereby accepted. You are authorized to do the work as specified.

Client's Printed Name Acceptance: _____

Client's Authorized Signature of Acceptance: _____

Acceptance Date: _____

PO Box 525, Wharton, NJ 07885 * Phone: (973) 989-5888 * Fax: (973) 989-4211
www.psi-services.com

