

# CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY 23 Bldg 206

Date of Visit: 8/25/22

Location Address: FT TOTTEN NY

Contractor Personnel on Site:

JIMMIE, CHARLES, JACK

Work Performed: CLEAN CHILUA REPLACE CONTRACTORS  
REPAIR REPAIRMENT

Service Calls - PO/CSS#

255/607 WO 18694

Please take pictures and send with quote

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: JOHN VOUNLE

Date: 8/25/22

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: LOUIS GONZALO RFO S Date: 25 AUGUST 2022

Signed: [Signature]

Email: LOUIS - 19 - CDR.MO.CIV @ ARMY.MIL





Carrier

DO NOT FORK









WARNING LABEL  
DANGER - HIGH VOLTAGE  
DO NOT TOUCH  
ELECTRICAL  
EQUIPMENT  
OR WIRING  
WHEN THE UNIT IS ON

Carrier

DO NOT FORK

DO NOT FORK