

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 1872

Maximo Work Order No. 18692

Asset#:

Date Issued: 07/25/2022

Original Description: Repair pump station. Alarm continues to sound. Possible lighting strike

Description of Repairs: Arrived onsite for emergency service call, lift station was found to be hit by lightning. Performed emergency repair to reset controls and performed diagnostic. Number 2 sewer pump is not working. Install rigging, remove number 2 pump and install with government supplied spare pump. Once completed will check for proper operation

Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$0	\$	\$0

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material	Equipment Cost	Total Cost	CE Factor	Total Estimate
Incurred Diag X2 men @ 8 hours each =16 man hours @ 250.00 per hour = 2000.00 Repair x3 men@6hrs ea 18hrs@205.00= 3690.00	\$5690.00	\$0	\$	\$5690.00	1.03	\$5748.60

Please see attached estimate

ACAV SERVICES

July 27, 2022



ESTIMATE 072722 CSS1872

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY23 BLDG 200 SEWER LIFT STATION</p> <p>LIFT STATION STRUCK BY LIGHTING</p> <p>EMERGENCY REPAIR TO REST CONTROLS AND RUN DIAGNOSTICS</p> <p>LABOR (EMERGENCY)</p> <p>8 HRS 2 \$250.00</p> <p>NUMBER 2 SEWER PUMP FOUND NOT WORKING</p>		\$2000.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		INSTALL RIGGING REMOVE NUMBER 2 SEWER PUMP AND REPLACE WITH GOVERNMENT SUPPLIED SPARE PUMP CHECK SYSTEM		
		<u>LABOR</u> 18 HRS @ \$205.00 PER HOUR (3 MEN 6 HRS EACH)		\$3690.00
		TOTAL		\$5690.00

TOTAL \$5690.00



