

## Additional Funding Request

<b>Site: NY023</b>	<b>CSS # 20426 WO-2-5063</b>
Description of Repairs	<p>BLDG 200 ROOM 2007 2015          Perform Duct cleaning within (4) outlined offices only.          Apply plastic over the supply and return registers in each office.          Set up 1 AFD (air filtration device) in the air handler room that services these offices only in order to create negative air within the ductwork.</p> <p>Clean and disinfect ductwork including, supply and return registers. -          Clean and disinfect the accessible areas within the air handler including the fan unit.</p>
<b>Diagnosis: Initial Work Order CSS# 20426</b>	Vent and air duct cleaning buildings RM 2015 and 2017 2nd floor office.
Explanation of Additional Costs for Repairs	Labor and Material to Vent and air duct cleaning buildings RM 2015 and 2017 2nd floor office.
Additional Labor Cost to Perform Repairs	10 x 225.00 - \$2250.00
Additional Material Cost to Perform Repairs	\$175.00
Total Cost of Repair	\$2425.00
<b>Notes:</b>	