

Additional Funding Request

Site: NY023	CSS # 20941 WO-5593
Description of Repairs	Replace LED fixture in mens shower. Replace strip in use light in Electronics room. Install circuit blanks in circuit breaker panel space 19 and 20
Diagnosis: Initial Work Order CSS# 20941	Repair light in men's shower and install blanks in circuit panels #19 & #20.
Explanation of Additional Costs for Repairs	Labor and material to complete call
Additional Labor Cost to Perform Repairs	\$ 7x\$110.00 = \$770.00
Additional Material Cost to Perform Repairs	\$ 598.81
Total Cost of Repair	\$ 1368.81

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
9/4/2019	1176

Name / Address
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024

				Project
Description	Qty	Rate	Total	
Replace LED fixture in men's shower. Replace strip in use light in Electronics Room. Install breaker blanks in circuit Breaker panel space 19, 20. Electrical & Lighting	7	110.00 550.00	770.00 550.00T	
				Subtotal \$1,320.00
				Sales Tax (8.875%) \$48.81
				Total \$1,368.81