

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 21337

Maximo Work Order No.: 5619

Asset#: NA

Date Issued: 9/12/19

Original Description: Remove military plaques from loading dock hallway and install in Kaine hall

Diagnosis: Labor and material to

- Mobilization to the site with equipment needed (hand truck, carts, spackle, tape, paint, brushes, drill / screw gun, Hilti Wall Hangers, Protection Plywood for display cases).
- Remove (32) plaques from the Loading Dock Hallway
- Transport (32) plaques to where the Display Cases Reside
- Repair holes in the Loading Dock Hallway walls, where plaques were removed (with tape, spackle and paint)
- Protect existing Display Cases with erecting plywood protection shield
- Install (32) plaques above the Display Cases, with Hilti Wall Hangers (please some of these plaques weigh 300 + lbs)
- Disassemble Plywood used for protection of Display Cases
- Clean up work area daily and upon completion

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$1231.00		\$1231.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
72 X \$ 85.00	\$6120.00	\$1231.00		\$7351.00	90%	\$6615.90

Please see attached estimate

Note:

10-7-2019

Fort Totten - Plaques Relocation Quote

To: International Support Group
Attn: Ms. Michele Dubois (Site Supervisor)
Address: 9050 Pines Blvd., Suite 150, Pembroke Pines, FL 33024
Email: mdubois@internationalsupportgroup.com
Phone: (954) 900-1095

Location: Fort Totten, 200 Duane Road, Flushing, NY
RE: Service Request # CSS 21337 WO 2-5619

Scope of Work:

- Mobilization to the site with equipment needed (hand truck, carts, spackle, tape, paint, brushes, drill / screw gun, Hilti Wall Hangers, Protection Plywood for display cases).
- Remove (32) plaques from the Loading Dock Hallway
- Transport (32) plaques to where the Display Cases Reside
- Repair holes in the Loading Dock Hallway walls, where plaques were removed (with tape, spackle and paint)
- Protect existing Display Cases with erecting plywood protection shield
- Install (32) plaques above the Display Cases, with Hilti Wall Hangers (please some of these plaques weigh 300 + lbs)
- Disassemble Plywood used for protection of Display Cases
- Clean up work area daily and upon completion



10-7-2019

Fort Totten - Plaques Relocation Quote

BREAKDOWN OF COSTS:

ITEM DESCRIPTION	COST
Mobilization of equipment (hand trucks carts, spackle, tape, paint, brushes, drill / screw guns, Hilti Wall Hangers, Protection Plywood)	\$200.00
128 Hilti Heavy Duty Wall hangers @ \$4.75 each	\$608.00
Spackle, Tape, Paint, brush	\$95.00
Protection Plywood	\$128.00
Demobilization of equipment	\$200.00
Labor Needed: 3 men x 3 days x 8 hrs per day x \$85 per hour:	\$6,120.00
QUOTE TOTAL:	\$7,351.00

QUOTATION VALID FOR: 30 DAYS FROM QUOTATION DATE

ACCEPTANCE OF QUOTATION:

The above price, conditions and specifications are hereby accepted. You are authorized to do the work as specified. Payment schedule: Cost of all materials up front and balance upon completion of work.

QUOTE ACCEPTANCE:

Client's Printed Name: _____

Client's Acceptance Signature: _____

Date: _____