

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023 B118

Date of Visit: 12/11/19

Contractor Personnel on Site:

1. JOWEON

2. FELIX

Work Performed:

EMERGENCY

Preventive Maintenance - (Annual, Quarterly, Monthly, equipment identification, etc.)  
Service Orders - CSS 27954 WO 2-6500

Asset #	Qty	Asset Description
		FOUN LEAK IN HEATER
		UNIT IN BLDG 118
		CRASH AREA
		PURPOSES BLEEDER VALVE

**CERTIFICATION OF WORK**

To be signed by the Contractor:

Print Name: JOHN WORME

Date: 12/11/19

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: LOUIS CORBO Date: 11 Dec 2019

Signed: 

E-Mail: LOUIS.A.CORBO-CTR@MAIL.MIL











