

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY23 Bldg 206 Date of Visit: 8/7/23
Location Address: FT TOTTEN NY

Contractor Personnel on Site:
John J. Soto

Work Performed: DIAGNOSTIC ON SINK SINK IN 1ST FLOOR
Service Calls - PO/CSS# CSS94380 WO 23756 PB/00041072

Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: John Soto Date: 8/7/23
Signed: John Soto

To be signed by Facility Manager:
I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Louis Corbo Date: August 7, 2023
Signed: Louis Corbo
Email: Louis.A.Corbo.CIV@Army.mil

