

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 94887

Maximo Work Order No. 24291

Asset#:

Date Issued: 08/23/2023

Original Description: B121 RM1010B Leaking AC Unit in ceiling.

Description of Repairs: Service drain pan; replace pump; wash and clean coil; charge system with 6 lb of Freon

Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$1825.00	\$	\$1825.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material	Equipment Cost	Total Cost	CE Factor	Total Estimate
(2 men @ 8 hrs/ea) <u>16 @ 210.00</u> = \$3360.00	\$3360.00	\$1825.00	\$	\$5185.00	1.02	\$5288.70

Please see attached estimate

ACAV SERVICES

September 7, 2023



**ESTIMATE 090723 CSS94887 WO24283
PO100041085**

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 121)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 121) RM 1010B LEAKING AC UNIT IN CEILING UNIT NEEDS SERVICE DRAIN PAN REPLACE PUMP WASH/CLEAN COIL CHARGE SYSTEM WITH 6 LBS OF FREON		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>MATERIAL</u>		
		DRAIN PUMP		\$550.00
		6 LBS 410A FREON @ \$175.00 PER LB		\$1050.00
		FILTERS		\$75.00
		NITROGEN DYE CHECK TEST KIT		\$150.00
		TOTAL MATERIAL		\$1825.00
		<u>LABOR</u>		
		16 HRS @ \$210.00 PER HOUR		\$3360.00
		2 MEN 8 HRS EA		\$5185.00
		TOTAL		
				TOTAL \$5185.00

