

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023-24487 Date of Visit: 03-20-2020

Contractor Personnel on Site:

1. Rodon-Ari

#### Work Performed:

**Preventive Maintenance** -(Annual, Quarterly, Monthly, equipment identification, etc.)  
**Service Orders -**

Asset #	Qty	Asset Description
		REMOVE BUBBLING RUBBER ROOF AREA (APXM. 80 SQ.FT.). CLEAN THE AREA, LET IT DRY..
		Removed EPDM Rubber Roof on Area 80 sq ft, clean debris
		Sealed the drain and applied new EPDM rubber cover, sealed seams

---

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Arian Kodra Date: 03-20-2020


Signed: A r i a n K o d r a

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the

best of my knowledge, completed the stated work listed:

Print Name/Rank: Louis Corbo Date: 3-29-2020

Signed: 

E-Mail: louis.a.corbo.ctr.mail,mil







