

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY 23 AMSA Bldg 123

Date of Visit: 5/25/22

Location Address: FT TOTEN

Contractor Personnel on Site:

BOB LARSEN TEM

Work Performed: REPLACE VENT + REPAIRS IN OVER HEAD FAN
COIL UNIT, ROOF MAN LEFT

Service Calls – PO/CSS#

CSS 257 WO 17199

Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: JOHN WOHAM

Date: 5/26/22

Signed: [Signature]

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: LOUIS GONZALO RFOS Date: 26 MAY 2022

Signed: [Signature]

Email: LOUIS.GONZALO.CIV@ARMY.MIL

