

### CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023- 200

Date of Visit: 9/30/20

Location Address: Fort Totten

Contractor Personnel on Site:

DEEN ROWE

Work Performed: g Cleaned up water and installed condensate pump to catch water from pan, Also had to create a new drain from pan.  
Service Calls – PO/CSS# 25825

Please take pictures and send with quote

### CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: DEENVAUGHN ROWE

Date: 9/30/20

Signed: 

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Louis Corbo AFOS

Date: 10/1/2020

Signed: 

Email: louis.a.corbo.ctr@mail.mil

