

Over and Above Estimate

Region:2

Location: NY023

CSS #: 26900

Maximo Work Order No. 10314

Asset#

Date Issued: 10/01/2020

Original Description: Diagnose and repair 3 consecutive solar lights on side staircase entrance to B200 that are out.

Diagnostic: Remove and install four (4) new batteries for solar walkway

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$1832.00		\$1832.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
10.5 hrs@ 185.00 Including 2.5 hours of diagnostic	\$1942.50	\$1832.00		\$3774.5	.90%	3397.05

Please see attached Estimate,



MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
10/16/2020	1213

Name / Address

International Support Group
9050 Pine Blvd., Suite 150
Pembroke Pines, FL 33024

