

Over and Above Estimate

Region:2

Location: NY023

CSS #: 26942

Maximo Work Order No. 10315

Asset#

Date Issued: 10/02/2020

Original Description: Repair Compressor in B124, non-operational

Diagnostic: Install new sewage control panel, see attached scope of work

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$2855.00		\$2855.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
6 hours@ 220.00 plumber 2 hours@ 248.00 Electrician	\$1816.00	\$2855.00		\$4671.00	.90%	4203.90

Please see attached Estimate,



ACAV SERVICES

October 8, 2020



ESTIMATE 100820 CSS26942

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	CC	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 BLDG 124 COMPRESSOR NOT WORKING DEFECTIVE MANIFOLD REMOVE AND REPLACE COMPRESSOR MATERIAL 1EA GAST MODEL 8HDM-10-M855 2HP 230/440 3 PHASE COMPRESSOR LABOR 6HRS @ \$220.00 (PLUMBER) 2HRS @ \$248.00 (ELECTRICIAN) TOTAL		
				\$2855.00
				\$1320.00
				\$496.00
				\$4671.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581