

## CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023-200

Date of Visit: 1/12/21

Location Address: Fort Totten

Contractor Personnel on Site:

Deen Rowe

Work Performed: g Replaced Combination Gas Valve on Hot Water Boiler #2.  
Changed two pipes on gas line also.

Service Calls - PO/CSS#

**Please take pictures and send with quote**

## CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: I Deen Vaughn Rowe

Date: 1/12/21

Signed: I Deen Vaughn Rowe

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Louis Corbo AFOS Date: 1/13/21

Signed: Louis Corbo

Email: louis.a.corbo.ctr@mail.mil

