

Additional Funding Request

Site: NY023	WO# 11087 CSS # 27702
Description of Repairs	Drain System, install scaffolding, replace valve, refill system.
Diagnosis: Initial Work Order CSS# 27702	Replace check valve on domestic water line in building #124
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	10 hrs @ \$220.00= \$2200.00
Additional Material Cost to Perform Repairs	\$255.00
Total Cost of Repair	\$2455.00

ACAV SERVICES

November 23, 2020



ESTIMATE 112320 CSS27702

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 124</p> <p>LEAKING 4" DOMESTIC CHECK VALVE LOCATED IN THE CEILING (20FT)</p> <p>DRAIN SYSTEM</p> <p>INSTALL SCAFFOLDING</p> <p>REPLACE VALVE</p> <p>REFILL SYSTEM</p> <p><u>MATERIAL</u></p> <p>4" BRASS CHECK VALVE WITH MISC. FITTINGS</p>		\$255.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		LABOR 10 HRS @ \$220.00		\$2200.00
		TOTAL		\$2455.00
TOTAL \$2455.00				