

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023

Date of Visit: 11/8/2022

Location Address: _____

Contractor Personnel on Site:

Rodon

Work Performed: repair AMSA 12 fluid distribution system. Multiple hoses in the shop are inoperable, affecting the daily mission

Service Calls – PO/CSS# 31308

Please take pictures and send with quote

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Rodon Construction

Date: 11/8/2022

Signed: Adrain Kodra

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site.

Print Name/Rank: Peter Comito AFOS

Date: 8 November 2022

Signed: Peter Comito

Email: peter.d.comito.ctr@army.mil

