

ACAV SERVICES

July 8, 2021



ESTIMATE 070821 CSS31477 WO14386

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW P BOYLE
Customer ID#	NY023 (BLDG. 206 LOT)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 206 BACK PARKING LOT</p> <p>REMOVE LARGE TREE THAT FELL IN PARKING LOT VIC BLDG 206</p> <p>CUT UP AND REMOVE TREE AND ALL DEBI</p> <p>REMOVE STUMP</p> <p>BACK FILL WHOLE (STUMP)</p> <p><u>LABOR</u></p> <p>16 HRS @\$250.00 PER HOUR</p> <p>6 HRS @300.00 PER HOUR</p> <p>(BOB CAT OPERATOR)</p> <p>TOTAL</p>		<p>\$4000.00</p> <p>\$1800.00</p> <p>\$5800.00</p>

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 31477

Maximo Work Order No.14389

Asset#:

Date Issued: 07/07/2021

Original Description: tree fell in parking lot need removed Emergency

Description of Repairs: Remove large tree that fell in parking lot VIC BLDG 206, Cut up and remove tree and all debris, remove stump and back fill hole.

Non Pre-Priced Estimate:

Quantity	Line Item Number	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)					\$1800.00	\$1800.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
X2Men total man hours 16@ \$250.00=\$6600.00	\$4000.00		\$1800.0	\$5800.00	1.03%	\$5974.00

Please see attached estimate

