

Additional Funding Request

Site: NY023	WO# 14850 CSS #32129
Description of Repairs	<p>Remove and install new Zurn automatic flush valve motor for 1st floor men's bathroom</p> <p>Men's 1st floor toilet stall building 200- remove and install new vacuum breaker and diaphragm</p> <p>Building 128 Female 1st floor replace the Sloan diaphragm automatic and vacuum breaker</p> <p>Building 206 Males restroom toilet, remove and replace coupling, vacuum breaker, and diaphragm</p> <p>Building 206 Two men's urinal- one first floor remove and replace handle and diaphragm. Second floor men's urinal- remove and replace diaphragm.</p>
Diagnosis: Initial Work Order	3 toilet bowls in building #200, not working
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	<p>2 hr @ 85.00 = 170.00</p> <p>Incurred cost for diagnostic and repairs made <u>6 hr @ 85.00 = \$510.00</u></p> <p>Total Labor \$680.00</p>
Additional Material Cost to Perform Repairs	<p>Flushometer with 20% markup=\$306.25</p> <p>Material for repairs on toilets with 20% markup=\$309.01</p> <p>Total Material 615.26</p>
Total Cost of Repair	\$1295.26



ZURN

Actuator Assembly, Fits Brand Zurn

Item # 5WYG3

Mfr. Model # PEMS6000-HYM

UNSPSC # 40141616

Catalog Page # 2754

Country of Origin Taiwan. Country of Origin is subject to change.

Toilet flush-valve handle and push-button repair parts are components for replacing the lever or button flushing mechanisms used on manual flush valves (flushometers). Handle or push-button assemblies may need replacing when they leak, sag, or no longer activate flushing.

Compare this product

Image to zoom.

Web Price \$235.22 / each

Qty
1

Shipping

Expected to arrive

Ship to 75961 |

Shipping Weight

Ship Availability Terms

A

PACKING LIST						
SOLD TO ACCOUNT 887056979		PURCHASE ORDER NUMBER CSS32190	DELIVERY DATE AND TIME 09/09/2021 07:24	EMPLOYEE XBXM193	PAGE 1 OF 1	
INTERNATIONAL SUPPORT GROUP 9050 PINES BLVD STE 150 PEMBROKE PINES FL 33024-6400 CALLER DEENVAUGHN ROWE TELEPHONE NUMBER 7184133472		DEPARTMENT NUMBER REQUISITIONER	DBTR CODE CASH	SALES ORDER NUMBER 4424945415	DELIVERY 6522035409	
SHIP TO INTERNATIONAL SUPPORT GROUP INTERNATIONAL SUPPORT GROUP LLC 9050 PINES BLVD STE 150 PEMBROKE PINES FL 33024-6400		PO RELEASE NUMBER	CHECK NUMBER	CHECK AMOUNT	CASH REC'D/PAID WC	
ATTENTION		SPECIAL INSTRUCTIONS NONE	INVOICE WILL FOLLOW SALES TERMS AND CONDITIONS ON REVERSE SIDE THANK YOU FOR YOUR ORDER			
		CARRIER NAME NONE	# OF BOXES	FREIGHT TERMS PPA	DATE SHIPPED/PICKED UP	
ITEM DESCRIPTION	ITEM NUMBER	SHIP QTY	BACKORDER MESSAGE	TAX	UNIT PRICE	TOTAL
ADA Handle, Zurn	4HCY1	1		T	18.97	18.97
Diaphragm Assembly, Manual, Urinals	34TE18	1		T	34.16	34.16
Gasket, Zurn	21TE66	1		T	0.58	0.58
Diaphragm Assembly, Automatic, Toilets	4FEU8	1		T	61.64	61.64
Diaphragm Assembly, Manual, Toilets, 1.29	25CH53	3		T	36.74	110.22
Vacuum Breaker Assembly, Zurn	25CH47	3		T	3.65	10.95

THIS PURCHASE IS GOVERNED EXCLUSIVELY BY GRAINGER'S TERMS OF SALE, INCLUDING: (i) DISPUTE RESOLUTION REMEDIES, AND (ii) CERTAIN WARRANTY AND DAMAGES LIMITATIONS AND DISCLAIMERS IN EFFECT AT THE TIME OF THE ORDER, WHICH ARE INCORPORATED BY REFERENCE HEREIN. GRAINGER'S TERMS OF SALE ARE AVAILABLE AT WWW.GRAINGER.COM.

PRODUCT RETURN INSTRUCTIONS ARE AVAILABLE AT WWW.GRAINGER.COM/RETURNS

These items are sold for domestic consumption in the United States. If exported, purchaser assumes full responsibility for compliance with US export controls.

GRAINGER
FOR THE ONES WHO GET IT DONE

SAP DELIVERY

6522035409

I certify that if I am purchasing the material(s) as "materials of trade" as defined in the Hazardous Materials Regulations in Title 49 of the Code of Federal Regulations, I intend to use the material(s) in direct support of my principal business (which is not transportation), and I do not intend to resell the material, or transport them in a vehicle other than my own.

Shipping	0.00
Tax	20.99
Total	257.51

Visit our web site @ www.grainger.com

