

### Over and Above Estimate

**Region:** 2

**Location:** NY023

**CSS #:** 32219

**Maximo Work Order No.2-14843**

**Asset#:**

**Date Issued:** 08/18/2021

**Original Description:** Repair leaking check valve on water meter line, inside front door of OMS shop building #121

**Description of Repairs:** Replace defective backflow preventor leaking

#### Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$1843.00		\$1843.00

*Note: RS Means (Pre-Priced) not used in compiling this estimate.*

*Note: Subcontractor quote attached.*

#### Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
4 hours @ \$225.00	\$900.00	\$1843.00		\$2743.00	1.03%	\$2825.29

**Please see attached estimate**

# ACAV SERVICES

August 26, 2021



## ESTIMATE 082621 CSS32219 WO

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW P BOYLE
Customer ID#	NY023 (BLDG 124)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
<b>Payment Due</b>	NET 30	<b>Delivery Date</b>	N/A
<b>Salesperson</b>	JW	<b>Shipping Method</b>	N/A
<b>Payment Terms</b>	N/A	<b>Shipping Terms</b>	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<b>NY023 BLDG 121 (OMS)</b>		
		<b>REPLACE DEFECTIVE BACKFLOW PREVENTER (LEAKING)</b>		
		<b><u>MATERIAL</u></b>		
		<b>WATTS LF009M2QT BACKFLOW PREVENTER</b>		<b>\$1843.00</b>
		<b><u>LABOR</u></b>		
		<b>4 HRS @ \$225.00 PER HOUR</b>		<b>\$900.00</b>
		<b>TOTAL</b>		<b>\$2743.00</b>

### ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581