

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 32823

Maximo Work Order No.14937

Asset#:

Date Issued: 10/06/2021

Original Description: Wall hung vanity sinks fell off the wall and should be replaced with sink bases

Description of Repairs: Remove and replace two 20 in wall mounted sinks with vanity sinks and repair wall.

Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$1273.00		\$1273.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
16hours @ \$235.00	3760.00	\$1273.00		\$5033.00	.90%	\$4529.70

Please see attached estimate



ACAV SERVICES

October 10, 2021



ESTIMATE 101021 CSS32823 WO

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 206 (2ND FLOOR LATRINE)</p> <p>REMOVE AND REPLACE 2EA 20 IN WALL MOUNTED SINKS WITH VANITY SINKS AND REPAIR WALL</p> <p><u>MATERIAL</u></p> <p>2EA 20 IN VANITY WITH SINKS</p> <p>2EA MOEN BATHROOM FAUCETS</p> <p>4EA BRAIDED WATER LINES</p> <p>2EA 1 1/4 P TRAPS</p> <p>TOTAL MATERIAL</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		LABOR 16 HRS @ \$235.00 PER HOUR		\$3760.00
		TOTAL		\$5033.00
THIS QUOTE IS GOOD FOR 30 DAYS				

TOTAL \$5033.00