

Additional Funding Request

Site: NY023	WO# 16624 CSS #34605
Description of Repairs	Remove broken window and frame. Remove and replace broken glass with Plexi glass and repair frame
Diagnosis: Initial Work Order	Repair broken window in room 111 in building #330. Window has fallen out of frame and needs to be secured.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4Hours @ 225.00= \$ 900.00
Additional Material Cost to Perform Repairs	@\$65.00
Total Cost of Repair	\$965.00

ACAV SERVICES

February 22, 2022



ESTIMATE 022222 CSS34605 WO16624

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 330 RM 111</p> <p>REPAIR BROKEN WINDOW AND FRAME</p> <p>REMOVE AND REPLACE BROKEN GLASS WITH PLEXI GLASS AND REPAIR FRAME</p> <p><u>MATERIAL</u></p> <p>1EA 4X5 PLEXI GLASS SHEET (COMMERCIAL GRADE)</p> <p><u>LABOR</u></p> <p>4 HRS @ \$225.00</p> <p>TOTAL</p>		\$65.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581